VERSION WITH MARKINGS TO SHOW CHANGES MADE

IN THE SPECIFICATION

The paragraph on page 9 beginning at line 5 has been replaced with the following paragraph:

The second instrument 130 includes one or more irrigation ports 136, 138, 140 for introducing irrigation fluid into the eye capsule 106 as indicated by the arrows 140-142.

Please replace the paragraph on page 9 beginning at line 28 with the following paragraph.

The irrigation ports 138, 140, 152, 154 are preferably spaced apart axially on the shaft 132, 148 respectively or, as illustrated in Figure 5, there may be also space radially about the shaft. The size of the ports 138, 140, 152, 154 may be 0.6 to 1.5mm in order to introduce irrigation fluid 164 at the rate of 20 - 60cc/min. The irrigation port 138, 140, 152, 154 size and location is dependant upon surgeon technique and incision location.